

87/1049/2021/IT_Cell

460

Regional Office, Gurugram (S)
Haryana State Pollution Control Board

3rd Floor, HSIIDC Complex, IMT Manesar, Gurugram
 Website – www.hspcb.gov.in E-Mail - hspcbrogrs@gmail.com
 Tele No. 0124-2290207, 0124-2290208

Kind Attn: Senior Environmental Engineer –IT (HQ)

To
 The Member Secretary
 Haryana State Pollution Control Board
 Panchkula

Sub: Regarding information of M/s TEJA CONSTRUCTION CO., RAISEENA ZONE, TEHSIL- SOHNA, DISTT.- GURUGRAM having HROCMMS ID 14GUSO1018390

Ref: Head Office letter no. IT-34D/14 dated 16-04-2021

In this connection, it is submitted that as per the inspection conducted by the field officer, the above said unit was found dismantled. Therefore status of the unit may be updated in HROCMMS as dismantled unit. The detail is as under:-

1.	Name & address of the unit	M/s TEJA CONSTRUCTION CO. , RAISEENA ZONE, TEHSIL- SOHNA, DISTT.- GURUGRAM
2.	HROCMMS ID	14GUSO1018390
3.	Latitude &Longitude of the unit	Not Available
4.	Operational Status	Dismantled
5.	Status of consent / authorization under HWM Rules	01.04.2016 to 30.09.2020
6.	Request letter permanent closure of unit, if available	Not Received
7.	Date of dismantling of unit, if available	01.09.2020
8.	Photographic evidence of dismantling unit, if available	Not Available
9.	Recommendation	Sh. Navneet Bhardwaj, AEE, Field Officer, HSPCB Gurugram Region South has conducted inspection on dated 01.09.2020 and during inspection it was found that the said unit has dismantled from the site. Therefore status of the unit may be updated in HROCMMS as dismantled unit.

Submitted for kind information and further necessary action please.

DA/Inspection report

Regional Officer
Gurugram Region (S)

Signed by Sandeep Singh
Date: 25-06-2021 13:09:36
Reason: Approved

461



Regional Office, Gurgaon South
HARYANA STATE POLLUTION CONTROL BOARD

SPOT INSPECTION REPORT

1.	Name of the Unit	Teja Construction Co. Paiseena Zone, Sohna Gurgaon.
2.	Date of Inspection	1-9-2020
3.	Name of Officer	Naveet Bhardwaj, AEE
4.	Name of Representative of the unit	
5.	Whether obtained NOC or not	
6.	Whether applied for consent or not	
7.	Product	
8.	Manufacturing Process	
9.	Discharge of the unit (i) Domestic (ii) Trade	
10.	Source of Trade Effluent (ETP/STP installed or not)	
11.	Source of Air Emission and Status of APCM (Installed / Not installed)	
12.	Hazardous Waste Generation/ Status	
13.	No. of D.G. Sets	
14.	Any other Remarks	Unit inspected in reference to mandatory inspection and during inspection unit found dismantled from site

Signature of the Representative of the Unit

Signature of the Verifying Officer
HSPCB, Gurugram Region (South)